




ASSEMBLY INSTRUCTION




ASSEMBLY INSTRUCTION




14 pcs



M6x40: 12pcs




M6x55: 4pcs



M6x110: 12pcs





1 pcs




4 pcs

Step 1




Lock 50%



(A) x1



(B) x1




Step 2




Lock 50%


(C) x1



(D) x1




Step 3




Lock 50%

Step 4




Lock 100%






Step 5








Lock 100%

Finish







ASSEMBLY INSTRUCTION




Step 3





Lock 50%

Step 4




Lock 100%







Step 5



Lock 100%



Finish






ASSEMBLY INSTRUCTION

Step 1




Lock 50%


(E) x1





(F) x2



(G) x2





Step 2




Lock 50%

Step 3





Lock 50%

Step 4



Lock 100%

Step 5



Lock 100%

Finish

